









DISPONIBILIDADE DE INFRAESTRUTURAS

2º TRIMESTRE 2022

		LIS		OPO	FAO	PDL	FNC	
		PICO	FORA DE PICO					
	PISTA	● 100%	● 100%	● 100%	● 100%	● 100%	● 100%	● 100%
	STANDS	● 100%	● 100%	● 100%	● 100%	● 100%	● 100%	● 100%
	SISTEMA DE TRATAMENTO DE BAGAGEM							
	Partidas	● 100%	● 100%	● 100%	● 100%	● 100%	● 100%	● 100%
	Transferências	● 100%	● 100%	● N.A.	● N.A.	● N.A.	● N.A.	● N.A.
	Chegadas	● 99,99%	● 99,99%	● 100%	● 100%	● 100%	● 100%	● 100%
	HBS	● 99,98%	● 99,99%	● 99,99%	● 100%	● 99,83%	● 99,99%	● 99,99%
	SSBD	● 99,57%	● 99,75%	● N.A.	● N.A.	● N.A.	● N.A.	● N.A.
	SISTEMAS CRÍTICOS DE TI							
	CUPPS	● 100%	● 100%	● 100%	● 100%	● 100%	● 100%	● 100%
	GO	● 100%	● 100%	● 100%	● 100%	● 100%	● 100%	● 100%
	FIDS	● 100%	● 100%	● 100%	● 100%	● 100%	● 100%	● 100%
	PONTES TELESCÓPICAS	● 99,93%	● 99,92%	● 100%	● 100%	● N.A.	● N.A.	● N.A.

		LIS	LIS	OPO	FAO	PDL	FNC
		PICO	FORA DE PICO				
	RECOLHA DE BAGAGEM						
	Primeira bagagem % bagagens entregue em x minutos	● 86,15%	● 80,24%	● 88,07%	● 85,27%	● 98,36%	● 93,37%
	Última bagagem % bagagens entregue em x minutos	● 88,68%	● 87,32%	● 96,65%	● 95,51%	● 95,89%	● 98,23%
	CONTROLO DE SEGURANÇA RX						
% passageiros processados em x minutos	● 98,84%	● 96,87%	● 90,56%	● 99,41%	● 97,10%	● 94,59%	
	EQUIPAMENTO DE APOIO À MOBILIDADE						
	Escadas rolantes	● 99,36%	● 99,42%	● 99,99%	● 100%	● N.A.	● 99,96%
	Tapetes rolantes	● 99,13%	● 99,14%	● 100%	● 100%	● N.A.	● N.A.
	Elevadores	● 99,03%	● 99,00%	● 99,99%	● 100%	● 96,78%	● 99,17%